# PHASE 1: Arenas Community Center, Guánica Emergency Center



#### Equipo de Voluntarios / Volunteering Group



Yanel de Angel

FAIA, Principal, Perkin&Will / Co-founder resilientSEE-PR



Tamara Perez

Designer, AiT, AIA Associate / resilientSEE-PR



**Gaston Saboulard** 

Designer, Toro Arquitectos / resilientSEE-PR



**Nicole Ferrer** 

Designer, Perkins&Will / resilientSEE-PR



**Manuel Fontan** 

Engineer, PE, LEED AP, Resilient Equities / resilientSEE-PR



Bryan Markkanen

Architect, AIA, Elliott Workgroup / Individual Collaborator / resilientSEE-PR



**Marc Wouters** 

Architect & Urban Planner, RA, Marc Wouters Studio

/ resilientSEE-PR



Jesabel Rivera

MPH, CHES, Community Impact & Engagement Solutions, Co-founder Voluntariado de Ingenieros



**Ruben Velez** 

PE, Senior Engineer, Voluntariado de Ingenieros

#### **ARUP**

- Leah Morales
- Kyle Cepeda

#### Unidos por Arenas, Inc.

- Luis Omar García-Mercado
- Sofia Ramos, secretaria
- Luz
- Virgen Rosado
- Juana Santiago Matos
- Sofia Ramos Bonilla
- Heidi Lopez
- Lillian

#### Nuestra Escuela

Angel Perez Soler

## **Project Objectives**

Transform the school into a resilient community center.

Evaluate existing building systems.

Develop an implementable concept.


Recommend strategies to transform the building and equip it.


Help the community raise funds by providing technical assistance and drawing illustrations.




Escuela María del Rosario C. Claudio

The María del Rosario C. Claudio School is located on Main Street - route 332 -Comunidad Arenas, Guánica, P.R.








## **Project Activities**

- Site Visits
- As-Built Documentation
- Existing Conditions Assessment
- Structural Certification
- Solar Panel System Peer Review
- Program & Adjacencies
- ✓ Architectural Room Layouts & Equipment List
  - Implementation Grants / Donations














Existing ramp system and existing stairs.



**Arenas Community Emergency Center** 

#### GOBIERNO DE PUERTO RICO COMITÉ DE EVALUACIÓN Y DISPOSICIÓN DE BIENES INMUEBLES

#### RESOLUCIÓN 2020-117

#### 26 DE OTUBRE DE 2020

RESOLUCIÓN DEL COMITÉ DE EVALUACIÓN Y DISPOSICIÓN DE BIENES INMUEBLES, PARA AUTORIZAR AL DEPARTAMENTO DE TRANSPORTACIÓN Y DEGRAS PÚBLICAS SUSCRIBIR UN CONTRATO DE ARRENDAMIENTO CON LA ENTIDAD UNIDOS POR ARENAS INC. PARA OCUPAR Y UTILIZAR EL PLANTEL ESCOLAR EN DESUSO MARIA DEL ROSARIO C. CLAUDÍO. LOCALIZADO EN DUÁNICA

POR CUANTO


Mediante la Ley Núm. 26-2017, Ley para el Cumplimiento con el Plan Fiscal (en adelante "Ley 26"), se decidro como politica pública la mejor utilización de las propiedades immebles en desuno, con el propietto de allegarle mayores recursos el erario, y propiciar que dicias propiedades sea utilizadas para actividades de bienestar común ylo desarrollo económico, creando un procedimiento eficiente y eficaz de venta de propiedades immunelos.

POR CUANTO

A nies fines, la Ley 26, creè el Comité de Evaluación y Disposición de Biennes Immebles (ma delante, el "Comité"), con el objetto de apercer desla ins faciliera successias para disposer de los bienes immebles de la Rama Ejecutiva. Actualmente, el Comité se rige conferen las disposiciones de Reglamento (ma de Evaluación y Disposición de Bienes Immebles del Gobierno, Reglamento 9133 de 9 de diciembro de 2019 (ma delante, el "Reglamento Ultico").

POR CUANTO

Unidos por Arenas, Inc. es una corporación sin fines de lucro debidamente inscrita en el Departamento de Estado con el número 447326 (en adelante, la "Entidad"). El El 22 de julio de 2020 se recibió propuesta del Sr. Luis O. García Mercado, Presidente de la Entidad. en la cual solicita el arrendamiento para ocupar y utilizar



#### **Spaces Program**

• Golden Age Center

#### **Community Services (flexible)**

- Physical Health
- Mental health
- Legal Help
- Safe Housing and Inspection
- Medical Dispensary ------ Community Reintegration
- Computer center Training / Tutorials / Studies
- Gym
   Machines & Weights
- Warehouse (2) **Food vs Equipment**
- Toilets Gender Inclusive
- Kitchen


First floor


- Dining room 


  → Multipurpose room
- Emergency Center Administration & Communication
- Community Garden Food Bank


**Second Floor** / Require elevator to comply with ADA regulation

- Community Micro-Enterprises
- Multiple uses











**Existing Rampa**Estimated Rampa Rise 7'-6" Estimated Rampa Existing Run: 76'



View of two rampas side by side Conceptual Proposal March 5, 2021



Existing Aerial View



 $\label{thm:connection} \mbox{ View of proposed filling of existing rampa to widen connection between buildings}$ 




Alternate 1. Basic Rampa Alternative
Estimated Rampa Rise 7'-6"
Estimated Rampa Run: 99' including required landings
NOT FOR CONSTRUCTION



Aerial View



View From Street Entrance Conceptual Proposal March 5, 2021



Alternate 2. Rampa with Outdoor Classroom
Estimated Rampa Rise 7'-6"
Estimated Rampa Run: 99' including required landings
NOT FOR CONSTRUCTION



View From Street Entrance Conceptual Proposal March 5, 2021



Aerial View



Outdoor Stepped Area for Classroom / Meetings

## **Structural System**

#### **URGENT REPAIRS**

- 1. Bending Failures in Two Beams: It is expensive to repair, but with FRP (Fiberglass Reinforced Plastic) it will be easy to install.
- 2. In most spaces, the block wall adheres to the column producing the short column effect. The infill concrete block wall is not directly connected to the column, but there is a joint. It is expensive to fix but a wall strip needs to be replaced and a rubber filler applied to allow the spine to flex.
- 3. Cracks in the floor of the Principal's Office on the second level.
- 4. Large crack in dining room column, should be investigated as oil paint is masking it. This also happens elsewhere.

Observations




## **Structural System**


#### OTHER REPAIRS AND RECOMMENDATIONS

General deterioration, exterior cracks must be sealed to prevent moisture and water from entering the walls.



#### "Short Column Condition"






Ductile flexural failure is desired. If detail for assumed full column length case is used, fails in shear.


Full Length Column








#### Short Column





$$V = \frac{2 \times M_p}{L_{/3}}$$

$$V = \frac{6 x M_p}{L}$$



## PHASE 2: Arenas Community Center, Guánica Emergency Center

**Community Kitchen Design** 



#### Equipo de Voluntarios / Team of Volunteers – Diseño Cocina Comunitaria / Community Kitchen Design



FAIA, Principal, Perkin&Will / Co-founder

resilientSEE-PR



Interior Project Designer, Perkins&Will

/ resilientSFF-PR



Designer, Perkins&Will / resilientSEE-PR



Designer, Perkins&Will / resilientSEE-PR



Tarah Schroeder

Executive Principal Ricca Design Studios



Jeremy Kittelson

Principal Ricca Design Studios



**Carly Maszle** 

Associate Ricca Design Studios




Amazing kitchen and back-of-the house design! resilientSEE-PR is thankful for the Ricca team partnership!




We are thankful to Robert White from Envision Strategies (partner to Ricca Design Studios) for helping with project kick off.



#### As-built drawing



### **Equipment Plan**

















#### **Dining Furniture Layout Options**











**Dining Option 1** 


**Dining Option 2** 

**Dining Option 3** 

**Presenter Option** 







**Meeting Option** 

**Meeting Alternative Option** 

**Ballroom Option** 



## THANK YOU.